



NEXA

Hybrid Range of

Veneers

E-mail : woodlineveneers@gmail.com
Follow us at   [woodline decorative veneers](#)



NEXA

Hybrid Range of

Veneers



Scan QR Code
For E-Catalogue

About us

Our Mission

To be the benchmark by which all interior product companies define themselves are globally admired for people, partnerships, quality & innocation.

Our Vision

To be global market leader via innovation and customer focus, while building a culture of continuous improvement.

The innovation by woodline has been introduced keeping in mind the luxury needs of smart architects and builders for their projects which imparts a bold and stunning look to the interiors.

As one of the leading manufacturers of Wood Veneers we enable a huge variety for our clients to choose from. We cater to bulk orders for clients in all parts of India. We also make arrangements for fulfilling the individual specifications desired by the clients, if any.



HOT-MELT
THREAD SPLICING



100%
GURJAN BASE



BORER &
TERMITE RESISTANT

Index



GERMAN SANDING
TECHNOLOGY



GLUE LINE
PROTECTION



BOILING WATER
RESISTANT

WG Woodline Gold Ipar (Italy)

WG-1	8x4
WG-2	8x4
WG-3	8x4
WG-4	8x4
WG-5	8x4
WG-6	8x4
WG-7	8x4
WG-8	8x4
WG-9	8x4

Gem Ipar (Italy)

G-1	EV DUSKY FOREST	8x4
G-2	E VINTAGE GREY	8x4
G-3	EBONY CROWN	8x4
G-4	NEO INDONESIAN EBONY	8x4
G-5	NEO DTC	8x4
G-6	E EXOTIC OAK CROWN	8x4
G-7	DYED ASH CROWN SAND GREY	8x4
G-8	E WEAVY OAK	8x4
G-9	DYED ASH CROWN NIGHT GREY	8x4
G-10	E CHEDDER GREY CROWN	8x4
G-11	E STEEL GREY CROWN	8x4
G-12	DYED OAK QRT ARMANI LIGHT GREY	8x4
G-13	CALIFORNIA WALNUT	8x4
G-14	DYED SYCAMORE CROWN ICE WHITE	8x4
G-15	DYED SILVER CLUSTER BURL	8x4
G-16	DYED SILVER BIRD EYE MAPLE BURL	8x4

G-17	DYED CHOCO LADDER BLOCKS	8x4
G-18	DYED LACE WOOD HILL BROWN	8x4
G-19	DYED BLOCK GREY	8x4
G-20	DYED SUKUPIRA MONSOON BLACK	8x4
G-21	DYED GREY RAIN SPLASH	8x4
G-22	DYED FIGURED SYCAMORE DUSKY GREY	8x4
G-23	DYED FIGURED SYCAMORE CHOCO GREY	8x4
G-24	DYED FIGURED MAPLE NATURAL BEIGE	8x4
G-25	DYED FIGURED MAPLE ENGLISH BEIGE	8x4
G-26	DYED OAK QTR SAHARA BROWN	10x4
G-27	DYED OAK QTR MEDITTERENEAN GREY	10x4
G-28	CALIFORNIA WALNUT	10x4
G-29	DYED OAK QTR MEDITTERENEAN WHITE	10x4
G-30	DYED ASH CROWN SILVER BROWN	10x4
G-31	DYED SYCAMORE CROWN ICE WHITE	10x4
G-32	DYED ASH CROWN MONSOON GREY	10x4
G-33	DYED ZEBRANO MISTRY BROWN	10x4
G-34	DYED OAK RIFT MILANO BROWN	10x4
G-35	DYED GREY RAIN SPLASH	10x4
G-36	DYED FIGURED MAPLE NATURAL BEIGE	10x4
G-37	DYED FIGURED MAPLE ENGLISH BEIGE	10x4
G-38	E-AMERICAN WALNUT CROWN	10x4
G-39	E-AMERICAN WALNUT QTR	10x4
G-40	E-FLITCH TEAK	10x4
G-41	E-GRAINLESS TEAK	10x4
G-42	EV-BURMA TEAK DARK GRAIN	10x4

WP (Woodline Premium) Busnelli (Italy)

WP-1	ASH Q/C	8x4	10x4
WP-2	WHITE OAK CROWN	8x4	10x4
WP-3	TEAK CROWN	8x4	10x4
WP-4	WALNUT CROWN	8x4	10x4
WP-5	DYED OAK Q/C SILVER	8x4	10x4
WP-6	GRAINS DYED OAK DESIGNER	8x4	10x4
WP-7	DYED OAK CROWN	8x4	10x4
WP-8	DYED OAK CROWN	8x4	10x4
WP-9	DYED OAK CROWN	8x4	10x4
WP-10	DYED OAK Q/C	8x4	10x4
WP-11	WALNUT Q/C	8x4	10x4
WP-12	MACASSAR EBONY	8x4	10x4
WP-13	SWISS EBONY	8x4	10x4
WP-14	WALNUT Q/C	8x4	10x4
WP-15	DYED OAK Q/C	8x4	10x4
WP-16	DYED OAK DARK GREY	8x4	10x4
WP-17	TEAK Q/C	8x4	10x4
WP-18	WHITE OAK Q/C	8x4	10x4
WP-19	DYED OAK Q/C	8x4	10x4
WP-20	OAK GREEN TINCH	8x4	10x4
WP-26	BALANCED OAK	8x4	10x4
WP-27	DEEP EUROPEAN WALNUT		10x4
WP-28	PLANKED OAK DESIGN		10x4
WP-29	WALNUT DESIGN		10x4
WP-30	DEEP OAK		10x4


WG WOODline GOLD

Ipar (Italy)

Crafted while keeping in mind the beauty found in the natural flaws of wood, this Gold Collection will outshine all other works of art. Nexa's ADT technology which involves using nailing and sawing to create a rustic and rugged texture makes this collection a unique display of perfect imperfections.



NEXA



8ft
6ft
4ft
2ft
0ft



8ft
6ft
4ft
2ft
0ft



Gem series

Ipar (Italy)

Upscale and classy, these veneers are intended for those who expect and appreciate the best. Available in a wide range of wonderful designs, their patterns will add a touch of exquisiteness to your furniture and interior.



NEXA



GEM
series

8ft
6ft
4ft
2ft
0ft



NEXA

8ft
6ft
4ft
2ft
0ft



8ft
6ft
4ft
2ft
0ft



8ft
6ft
4ft
2ft
0ft



8ft
6ft
4ft
2ft
0ft



Veneer Used G-17




8ft
6ft
4ft
2ft
0ft



8ft
6ft
4ft
2ft
0ft

Veneer Used G-6



8ft
6ft
4ft
2ft
0ft



10ft
8ft
6ft
4ft
2ft
0ft



GEM

series



10ft
8ft
6ft
4ft
2ft
0ft



10ft
8ft
6ft
4ft
2ft
0ft


NEXA



10ft
8ft
6ft
4ft
2ft
0ft



10ft
8ft
6ft
4ft
2ft
0ft





Veneer Used G-20



WP WOODline Premium BUSNELLI (ITALY)




A fascinating play to create a breath-taking effect the Premium Veneer is a one of a kind offering from the texture collection.

A special process of undulating the veneer brings out the grains and crowns in the veneer giving it a three-dimensional effect.



NEXA





Veneer Used **WP-7**




27



28

Veneer Used **WP-6**





WP
series



NEXA



CARE & MAINTENANCE

HOW TO TAKE CARE OF YOUR VENEERS

The on-going care of finished veneered surfaces depends largely on the type and quality of coating applied. In general, veneer surfaces should not be left wet/damp or with staining materials on them, such as dark fruit juice/wine. They should not be cleaned with harsh cleaners or chemicals that affect the surface finish. Sharp edges are potential problem zones for breaks or cracks in the coating.

Dusting: Use only a soft dry cloth or feather duster.

Polishing: Use a high-quality furniture polish and a soft dry cloth. It is recommended the polish used does not contain any silicone as this may cause re-coating or refurbishment problems at a later date. Abrasive polishes should be avoided.

Extreme temperature changes:

The expansion or contraction of the timber due to extreme temperature changes may cause damage to the surface coating. Care should be taken in an air-conditioned or heated environment to keep the temperature fluctuations within reasonable limits. Use heat-resistant placements under hot food and beverages to avoid heat damage.

Spillages: All spillages should be cleaned with a damp cloth as soon as possible. Moisture may cause damage to the coating. High humidity, steam and excessive water contact with the coating may cause the coating, it causes white marks on the surface of the veneer. Any chemical substances and alcohol should be removed immediately if spilled on a veneered surface.

Dirty or Greasy Marks: First wipe it clean with a dry cloth, then use a lightly dampened cloth with a mixture of water and a high-quality furniture polish. Persistent dirty or greasy marks may be removed by mild, non-abrasive proprietary cleaners appropriate to the cleaner should be sought from the surface coating or cleaner manufacturer. The effect of the cleaner on the surface should be tested on a hidden or a less conspicuous section on the finished veneer surface.

Direct Sunlight: Direct sunlight should be avoided on all internal veneered surfaces as fading, bleaching or colour changes of the surface coating and of the veneer may occur. Excessive sunshine may dry the veneer surface more quickly than the veneer substrate thereby causing small surface checks parallel to the grain to appear and possibly damage the surface coating.

Polishing Process

- Stage 1** Surface cleaning
- Stage 2** Sealer Application
- Stage 3** Smoothing with higher grit sanding paper
- Stage 4** Desired polish application

Types of Polish

Lacquer
Melamine Polyurethane(PU)
Polycoat

